

- P2: Safety instructions
- P3: Contents
- P4: Assembly instructions
- P6: User manual
- P15: Service checklist

IMPORTANT SAFETY INSTRUCTIONS

SAFETY INSTRUCTIONS: DME-TXT NON + KEY LOCKED

WARNING - To reduce the risk of burns, fire, electric shock or injury to persons:

1. Close supervision is necessary when this unit is used by, or near children, invalids, or disabled persons.
2. Use this unit only for its intended use as described in this manual.
Do not use attachments not recommended by the manufacturer.
3. Never drop or insert any object into any opening other than the intended use of presenting sunglasses.

MAINTENANCE INSTRUCTIONS - Instructions for cleaning and user maintenance operations:


1. The exterior of a SECURE DISPLAY SYSTEM may only be cleaned with a non-static brush.
2. The SECURE DISPLAY SYSTEM has no user serviceable parts. All malfunctioning or damaged components are to be replaced by a service representative duly authorized by Frame Displays

INTENDED USE

1. The intended use of the Secure Display System is to display eyewear frames and sunglasses.
2. This product is for commercial use only.




12 positions 50551
or
16 positions 50552




70121 (2x)
55mm




70082 (4x)
Ø10x20mm




95077 (2x)
4,2x50mm



95068 (4x)
3,9x38mm




95012 (2x)
M4x25mm




95090 (4x)
M4x8mm


REQUIRED TOOLS



Ø 4,5 mm






PH2




2mm

- Included


1




2



70121 (2x)
55mm




95012 (4x)
3,9 x 38mm




3



95012 (4x)
M4 x 25mm



70082 (2x)



4



95090 (2x)
M4 x 8mm (2x)

